

# **INFRASTRUCTURE/ DEVELOPMENT**

**Abandoned, Incomplete and Substandard Projects**

**Sponsored by Federal, State, and Local Governments;  
Oil Companies and International Organizations  
since 2000**

**Part of the Citizen Report Card  
on Public Services, Good Governance and Development from 120 Niger Delta Communities**


Niger Delta Professionals for Development (NIDPRODEV)  
Effurun-Warri, Delta State, Nigeria  
January 2011

Sponsored by the European Union

This project was funded by the **European Union (EU)**. Based on a partnership agreement between the **EU** and the **Federal Republic of Nigeria**, the implementation responsibilities of the **EU INSIDE** programme belong to the **National Planning Commission (NPC)**.



**Niger Delta Professionals for Development (NIDPRODEV)** is a Nigerian non-governmental organization that has worked in the Niger Delta for over 11 years on conflict management, community development, good governance, livelihood issues, and data collection and analysis. The **Leadership Center for Peace, Integrity and Transformation** is NIDPRODEV's parent organization.



**NIDPRODEV**

PTI Road, Plot 211, Fashion-N-Vogue Building  
Effurun-Warri, Delta State  
234 802-327-0549, 234 805-851-1591

## METHODOLOGY


1. NIDPRODEV programme officers visited 120 Niger Delta communities (6 States, 13 Local Government Areas) between August and December 2010. All programme officers possessed the local language skills of the community in which they collected information about public services, good governance, and infrastructure/development projects.
2. Community leaders and members were asked to identify incomplete, abandoned, and substandard infrastructure projects that were sponsored in their communities since 2000. NIDPRODEV programme officers then conducted a transect walk of each community with a community representative who pointed out each project and answered the questions on the “project profile” form, from which the data contained herein were extracted.
3. In some communities, NIDPRODEV programme officers noted that community leaders instructed NIDPRODEV programme officers to exclude from taking note of certain incomplete, abandoned or substandard infrastructure projects that they might observe during the transect walk. NIDPRODEV agreed to these limitations imposed by certain community leaders. Therefore, not all abandoned, incomplete or substandard projects were reported.
4. NIDPRODEV did not take note of any completed, successful infrastructure projects, as that was not an objective of the project. Therefore, the information herein does not inform the reader of how many infrastructure projects the Sponsor has started in each LGA or how many infrastructure projects the Sponsor successfully completed in each LGA.
5. NIDPRODEV does not investigate or validate the accuracy of a community’s identification of which government agency, oil company or international organization is the sponsor of a particular infrastructure project nor contact the identified contractor for a response. The information collected and presented herein is derived entirely from the knowledge and perceptions of community members.

## TABLE OF CONTENTS

	<u>Page</u>
Summary of Number and Source of Abandoned, Incomplete and Substandard Projects .....	5
Graphic Illustrations of Summary .....	6 - 14
<u>By State and Local Government Area:</u>	
Projects Sponsored by the Federal Government of Nigeria .....	15
Projects Sponsored by the Niger Delta Development Commission (NDDC) (Federal Govt) ...	30
Projects Sponsored by State Governments .....	46
Projects Sponsored by Local Government Areas (LGAs) .....	77
Projects Sponsored by Oil Companies .....	90
Projects Sponsored or Co-Sponsored by International Organizations .....	102


State / LGA (number of communities assessed)	Number of Abandoned, Incomplete or Substandard Projects by the Sponsor of Such Projects						
	Fed'l Govt	NDDC (Fed Govt)	State Govt	Local Govt (LGA)	Oil	Int'l Orgs	TOTAL
ABIA STATE / Ukwu East LGA (9 communities)	5	9	7	0	1	1	<b>23</b>
ABIA STATE / Ukwu West LGA (8 communities)	2	8	4	3	11	2	<b>30</b>
BAYELSA STATE / Kolokuma/Opokuma LGA (10 communities)	14	0	16	1	0	3	<b>34</b>
BAYELSA STATE / Sagbama LGA (10 communities)	12	4	18	3	0	4	<b>41</b>
DELTA STATE / Ughelli South LGA (10 communities)	0	0	7	8	0	0	<b>15</b>
DELTA STATE / Uvwie LGA (10 communities)	0	1	5	3	0	1	<b>10</b>
DELTA STATE / Warri South LGA (10 communities)	0	2	8	1	0	0	<b>11</b>
IMO STATE / Oguta LGA (10 communities)	0	8	8	5	3	2	<b>26</b>
IMO STATE / Ohaji Egbema LGA (10 communities)	1	6	6	3	4	2	<b>22</b>
ONDO STATE / Ese Odo LGA (9 communities)	1	7	20	0	0	1	<b>29</b>
ONDO STATE / Ilaje LGA (9 communities)	0	11	9	0	3	1	<b>24</b>
RIVERS STATE / Obio-Akpor LGA (6 communities)	3	1	3	1	0	0	<b>8</b>
RIVERS STATE / Ahoada East LGA (9 communities)	2	0	9	3	0	0	<b>14</b>
<b>TOTAL</b>	<b>40</b>	<b>57</b>	<b>120</b>	<b>31</b>	<b>22</b>	<b>17</b>	<b>287</b>

**TOTAL NUMBER OF ABANDONED, INCOMPLETE AND SUBSTANDARD INFRASTRUCTURE PROJECTS  
identified by Community Members**




Abia State (17 communities), Bayelsa State (20 communities), Delta State (30 communities), Imo State (20 communities), Ondo State (18 communities), Rivers State (15 communities)

**SPONSORED BY FEDERAL GOVERNMENT (Ministries and NDDC combined)**  
**ABANDONED, INCOMPLETE AND SUBSTANDARD DEVELOPMENT PROJECTS**




Abia State (17 communities), Bayelsa State (20 communities), Delta State (30 communities), Imo State (20 communities), Ondo State (18 communities), Rivers State (15 communities)

**SPONSORED BY STATE GOVERNMENT**  
**ABANDONED, INCOMPLETE AND SUBSTANDARD DEVELOPMENT PROJECTS**



Abia State (17 communities), Bayelsa State (20 communities), Delta State (30 communities), Imo State (20 communities), Ondo State (18 communities), Rivers State (15 communities)


**SPONSORED BY LOCAL GOVERNMENT AREAS**  
**ABANDONED, INCOMPLETE AND SUBSTANDARD DEVELOPMENT PROJECTS**  
SOUTH EAST GEOPOLITICAL ZONE (Abia State and Imo State)



Abia State (Ukwa East LGA and Ukwa West LGA, 17 communities), Imo State (Oguta LGA and Ohaji Egbema LGA, 20 communities)

**SPONSORED BY LOCAL GOVERNMENT AREAS  
ABANDONED, INCOMPLETE AND SUBSTANDARD DEVELOPMENT PROJECTS**

SOUTH SOUTH GEOPOLITICAL ZONE (Baylesa State, Delta State, and Rivers State)



Baylesa State (Kolokuma/Opokuma LGA and Sagbama LGA, 20 communities), Delta State (Ughelli South LGA, Uvwie LGA, and Warri South LGA, 30 communities), and Rivers State (Obio-Akpor LGA and Ahoada East LGA, 15 communities)


**SPONSORED BY LOCAL GOVERNMENT AREAS**  
**ABANDONED, INCOMPLETE AND SUBSTANDARD DEVELOPMENT PROJECTS**  
SOUTH WEST GEOPOLITICAL ZONE (Ondo State)

There were no reported abandoned, incomplete and substandard development projects sponsored by Ese-Odo LGA or Ilaje LGA.

**SPONSORED BY OIL COMPANIES**

**ABANDONED, INCOMPLETE AND SUBSTANDARD DEVELOPMENT PROJECTS**

SOUTH EAST GEOPOLITICAL ZONE (Abia State and Imo State)



## **SPONSORED BY OIL COMPANIES**


### **ABANDONED, INCOMPLETE AND SUBSTANDARD DEVELOPMENT PROJECTS**

#### SOUTH SOUTH GEOPOLITICAL ZONE (Baylesa State, Delta State, and Rivers State)

There were no reported abandoned, incomplete and substandard development projects sponsored by oil companies in any of the communities in Baylesa, Delta or Rivers States.

Baylesa State (Kolokuma/Opokuma LGA and Sagbama LGA, 20 communities), Delta State (Ughelli South LGA, Uvwie LGA, and Warri South LGA, 30 communities), and Rivers State (Obio-Akpor LGA and Ahoada East LGA, 15 communities)

**SPONSORED BY OIL COMPANIES**  
**ABANDONED, INCOMPLETE AND SUBSTANDARD DEVELOPMENT PROJECTS**  
SOUTH WEST GEOPOLITICAL ZONE (Ondo State)



Ondo State ( Ese Odo LGA and Ilaje LGA, 18 communities)

**ABANDONED, INCOMPLETE OR SUBSTANDARD  
INFRASTRUCTURE PROJECTS**

**SPONSORED BY**

**THE FEDERAL GOVERNMENT**

## FEDERAL GOVERNMENT

### Incomplete, Abandoned, and Substandard Projects Sponsored by Federal Government Ministries

[Each project status is written as it was recited to assessors. Assessments completed August through December 2010.]

(3 Geopolitical Zones, 6 States, 13 LGAs, 120 Communities)

STATE	LGA	NUMBER OF INCOMPLETE, ABANDONED AND SUBSTANDARD PROJECTS IDENTIFIED
Abia State (SE)	Ukwa East LGA	5
Abia State (SE)	Ukwa West LGA	2
Bayelsa State (SS)	Kolokuma/Opokuma LGA	14
Bayelsa State (SS)	Sagbama LGA	12
Delta State (SS)	Ughelli South LGA	0
Delta State (SS)	Uvwie LGA	0
Delta State (SS)	Warri South LGA	0
Imo State (SE)	Oguta LGA	0
Imo State (SE)	Ohaji Egbema LGA	1
Ondo State (SW)	Ese Odo LGA	1
Ondo State (SW)	Ilaje LGA	0
Rivers State (SS)	Obio-Akpor LGA	3
Rivers State (SS)	Ahoada East LGA	2
		<b>TOTAL: 40</b>

## ABIA STATE

### 1. Ukwa East LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Akirika Nta	Federal Ministry of Water Resources	Segnal Nig Ltd. & ROMAK Int. Ltd.	Water Intervention Programme	2007	The reservoir tank is rusty, producing coloured water. The distribution of pipes was not completely done. The generator that powers the bore hole has been stolen. Although the borehole produced water, they did not dig deep enough to get good water. For over six months now, the borehole has not produced water.
Obeaku	Federal Government, Ministry of Health	Enyinnaya Abaribe	Federal health Centre	2008	The project has not been roofed, there is no windows, and the building have not been plastered not to talk of supplying medical equipments and drugs. The project is Abia South Senatorial project by the federal Government.
Obeaku	Abia South Senatorial project	Sen. Adolf Wabara	Electrification	2002	The project is senatorial project anchored by former senate president (Sen. Adolf Wabara). In Obeaku community only electricity poles has been erected, no transformer, no cable for wiring.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ohambele	Federal Government	Adolphus Wabara	Federal Medical Centre	2002	The project was never done at all. There is no place to say work have started for the siting of the medical centre. On paper, however, it seems the project has been completed because when it reached the stage of supplying equipments and drugs, they were supplied and it was kept in the former senate president house (Adolphus Wabara) for over two years. Now both the equipments and the drugs are still in his house.
Ohambele	Federal Government	Adolphus Wabara (former senate president)	Bore hole (N500 Million) Project	2002	The tank reservoir was mounted but the distribution of the pipes is half done. The borehole project did not produce water for even one day.

## 2. Ukwa West LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Umuiku	Federal Government		Rural Intervention Water Scheme	2007	The tank reservoir was mounted and the generator house built but since the inception of the project, the scheme has never produced any water, not even for one day. Presently, the whole area has been overgrown with grasses.
Owaza	Petroleum Trust Fund (PTF)	HRM Eze Young Ogbonna	Bore Hole Water Scheme	2002	The project produced water for some time and stopped. The borehole seems not to be dug deep enough and some material used was of low standard. When the project stopped functioning, the traditional rulers cut off the pipes and sold them.

## BAYELSA STATE

### 1. Kolokuma/Opokuma LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Igbedi	Federal Government	no idea	Junior Secondary School Building (Ube)	2009	Construction stopped after foundation (DPC level)
Igbedi	Federal Government	London Brown	Cottage Hospital	2006	Construction stopped at roofing level.
Igbedi	Federal Government	no idea	Cottage Hospital (2)	2009	Construction stopped at DPC (after foundation) and Lintel Level
Okoloba	Federal Government	Frank Co. Nig. Ltd	extension of Rural Electrification	2008	The electrification was left at the 3rd phase of high/low tension drawing.
Okoloba	Federal Government	Elite Construction Company	Internal Road Network	2008	It was done below specification. There is no proper abatement and as such, the sand/tarred work was easily washed away. Even the drainage system was not covered with slabs.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Okoloba	Federal Government	Bena Const. Company	Concrete Jetty	2002/2003	The project construction was completed in 2003 but done with substandard/inferior material. As such, part of it was washed away by erosion the next year after completion.
Okoloba	Federal Government	Pamanek Nig. Ltd	Bore Hole water scheme	2007	The drilling was done, over-head tank also raised but the distribution channels are yet to be fixed.
Sabagreia	Federal Government	don't know	Federal Model health Centres	2002	Roofing levels at present, the structure has started cracking.
Sabagreia	Federal Government	Elite Construction Company	Road Construction	2004	Some of them was tarred below 2 inches tarring, while some of them was on ordinary ground. There was no drainage system, culverts are not enough while the few constructed ones are not well constructed.
Sabagreia	Federal Government	Elite Construction Company	Sabagreia/ Polako road	2007	Only 25% of the road was completed while 75% was just sand filled.
Sabagreia	Federal Government	Elite Construction Company	Sabagreia/ Polako Bridge	2007	After pilling the pillars, nothing else happened.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Kaiama	Federal Government	Ibrahim	Ware House	2009	Left at roofing level.
Orubiri	Federal Government	Zenith & Zenith Const. Company a Subsidiary of FCC	Sea Shore Pilling	2003	They left after mobilizing to the site. Since then, nothing has ever happened there again and erosion is fast eating up our sea shore.
Odi	Federal Government	Direct Labour	Public Address System	2009	All of the equipment was stolen.

## 2. Sagbama LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Trofani	Federal Government	Larry Koinyan	Youth Corper's Lodge	2002/2003	No furniture, no water.
Trofani	Federal Government	"Meet Me"	Landing Jetty	2000	They only erected poles.
Odoni	Federal Government	don't know	Water Project	2006/07	The bore hole is drilled, but no overhead tank.
Odoni	Education Trust Fund	don't know	3-classroom block	2002	Abandoned at DPC level

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Odoni	Education Trust Fund	Reed Alade	River Nun Sec. School Science Laboratory block	2009	Built only to roofing level.
Agbere	Federal Government	SONEC Engineering	Bore Hole water scheme	2006	It was abandoned after the raising of the tank. The water drilling was never done till date. No fixing the distribution channels.
Agbere	Federal Government	Pile Foundation Ltd.	Shoreline Protection	2004	Abandoned after mobilization to the site.
Adagbabiri	Federal Government	don't know	Solar water scheme	March 2010	It was abandoned after installation/drilling of bore hole, raising of the over-head tank but the solar system was not installed and there is no pumping machine to use it in the alternative way.
Sagbama	Federal Government of Nigeria	laego Ventures Ltd	Emergency Obstetrics Care unit	2010	The building is in progress (on going) and at roofing stage.
Sagbama	Federal Government	no idea	Rural Electrification	2009	It was left after the drawing of the high tension half way to Kiama. The transformer has not been linked to Kiama where it will now draw light to Sagbama.

<b>COMMUNITY NAME</b>	<b>SPONSOR</b>	<b>CONTRACTOR</b>	<b>PROJECT TYPE</b>	<b>START-ED</b>	<b>PROJECT STATUS</b>
Bulou-Orua	Federal Government	Fountain Construction Company (F.C.C)	Construction of Road with Bridge.	2002	Work is still ongoing and seriously in progress.
Ebedebiri	Federal Government	Shuina Construction Co. Ltd	Concrete Jetty	2006	The platform and the steps have been constructed but there is no hand rail.

## **DELTA STATE**

1. **Ughelli South LGA**: No abandoned, incomplete or substandard infrastructure projects identified.
2. **Uvwie LGA**: No abandoned, incomplete or substandard infrastructure projects identified.
3. **Warri South LGA**: No abandoned, incomplete or substandard infrastructure projects identified.

## IMO STATE

1. **Oguta LGA**: No abandoned, incomplete or substandard infrastructure projects were identified.

2. **Ohaji Egbema LGA**:

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Obiakpu	Federal Government	Engr. Nwakamma	rural borehole	2000	The project was abandoned at the level of erecting the tank stand. The borehole was sunk, tank stand installed, but no tank or distribution pipes yet.

## ONDO STATE

### 1. Ese Odo LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Igbotu	Federal Government of Nigeria	Aswalit Ventures Limited	Construction of motorized borehole	2008	The water has not been pumped to the tank.

2. Ilaje LGA: No abandoned, incomplete or substandard infrastructure projects identified.

## RIVERS STATE

### 1. Ahoada East LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ogbo	Federal Government	Hills Company Nig. Ltd	Borehole Water Scheme	2006	Overhead tank was hung. Since then, nothing else has been done on the site.
Edeoha	Federal Government	Direct Labour Agency	Edeoha/Ikata Road	2003	Abandoned after grading and pouring of laterite at some portion of the road.

### 2. Obio/Akpor LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Choba	Federal Government	don't know	Borehole Water Scheme	2003	Abandoned after tank was raised. Drilling has not taken place and as such water is not coming out.
Choba	Federal Government	don't know	Six classroom Block (Primary School)	2005	Abandoned after lintel stage; not roofed.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Woji	Federal Government of Nigeria	don't know	Health Centre	2005	<p>Contractor left after supplying hospital equipment and drugs. The building has been roofed but the finishing touches like plastering, electrical fittings and toilet facilities have not been done. Also, the building was underscored as it was built with substandard material and also the building design was not followed by the contractor. Therefore, at present, the roof is sagging, and the walls are irregular. Despite the poor construction, the contractor is still yet to be found.</p>

**ABANDONED, INCOMPLETE OR SUBSTANDARD  
INFRASTRUCTURE PROJECTS**

**SPONSORED BY**

**THE NIGER DELTA DEVELOPMENT COMMISSION (NDDC)  
(FEDERAL GOVERNMENT)**

**NDDC - Federal Government  
Incomplete, Abandoned, and Substandard Projects**

[Each project status is written as it was recited to assessors. Assessments completed August through December 2010.]

(3 Geopolitical Zones, 6 States, 13 LGAs, 120 Communities)

STATE	LGA	NUMBER OF INCOMPLETE, ABANDONED AND SUBSTANDARD PROJECTS IDENTIFIED
Abia State (SE)	Ukwa East LGA	9
Abia State (SE)	Ukwa West LGA	8
Bayelsa State (SS)	Kolokuma/Opokuma LGA	0
Bayelsa State (SS)	Sagbama LGA	4
Delta State (SS)	Ughelli South LGA	0
Delta State (SS)	Uvwie LGA	1
Delta State (SS)	Warri South LGA	2
Imo State (SE)	Oguta LGA	8
Imo State (SE)	Ohaji Egbema LGA	6
Ondo State (SW)	Ese Odo LGA	7
Ondo State (SW)	Ilaje LGA	11
Rivers State (SS)	Obio-Akpor LGA	1
Rivers State (SS)	Ahoada East LGA	0
		<b>TOTAL: 57</b>

## ABIA STATE

### 1. Ukwa East LGA

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Azumini	don't know	Borehole water scheme	2006	No overhead tank as reservoir, though the generator set has been installed but pipes has not yet been laid across the community. The few laid or used at the centre are substandard pipes as the break with short period of time.
Ohambele	don't know	Borehole water scheme	2008	The network pipes are yet to be fixed. The water produced from first and only operation till date is not drinkable maybe the bore hole are not deep enough. The overhead tanks has started rusting. The project is in four locations within the community.
Obohia	don't know	Borehole water scheme	2006	The bore hole has been drilled with overhead reservoir tank and pumping machine. The network pipes to distribute water across the community is halfway done. The project is yet to be commissioned but it has been test run.
Obeaku	Herbertec Construction Company	Ohambele Junction/ Water Side Road	2001	No work has begun on the road. The survey was done, but when the contract is been awarded, the bill of quantity was not given.

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Akwete (Umihueze)	Nevesco Nig. Ltd	Solar Power Street Lights	2006	The borehole was drilled, with overhead steel reservoir and other necessary connections, except network pipes across the community to supply water. It has never worked, not even once.
Akwete (Umihueze)	don't know	Mkporobe/ Akwete Road (construction)	2008	The road was graded and blinded it with coal tar, but yet to be tarred and no drainage system. The coal tar has a lot of potholes which make the road 60% non-motorable.
Akwete (Umihueze)	Icoru Nig Ltd	Borehole Water Scheme (solar powered)	2001	The borehole was drilled and overhead tank was mounted but the water has not started rushing. They did not drill deep enough to get water.
Ohuru Ndoki	don't know	2 Classroom Block with store and office	2000	The building was only roofed. It has no windows, doors, ceiling. It was never plastered. The environment has been overgrown with grasses. Other buildings in the primary school area need to be renovated too because of leaking roof, spoiled windows, and doors pulled out.
Ohuru Ndoki	don't know	Bore Hole Water Scheme	2000	Borehole has been drilled and overhead steel tank has been in place, but no pumping machine or pipe network. As of now, the overhead steel tank is bad because it has been affected by weather and rust.

## 2. Ukwa West LGA

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Owaza	HRM Eze Young Ogbonna	6 Classroom Block	2008	The building has been completed but some doors and windows have pulled away and consequently needs to be repaired.
Umudobia	Odaru Petroleum Ltd	Solar Powered Water Supply Scheme	2006	It is a water bore hole with a big overhead metal storage tank. It was completed and functioned for about 6 weeks before the solar panel was stolen. The position of the solar panel was not appropriate -- it was mounted on the ground instead of up over the tank. The pipes networking to distribute the water across the community were not completely done and the material used was substandard because they broke down within the 6 weeks. The community repaired some. A solar panel is needed to make it function again.
Obehie	don't know	Borehole Water Scheme	1991/ begun again in 2007	The water scheme has not produced a drop of water since 1991. The water tank has been mounted, generator and priming machine house had been built but the generating set supplied by the contractor was stolen. In 2007/2008, NDDC took over the project but up until now, it has not functioned.
Obehie	don't know	Six Classroom Block with an Office	2005	The flooring of the whole block is bad and it has broken off, so the blocks are needed to be re-floored. The building has been wired but not connected to power supply from PHCN. No comfort station for the pupils.

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Umuorie	J.A.S. Nkwocha & Sons	Health Centre	2005	Health Centre needs total renovation because some doors and windows have been pulled out. There is an opening in the roof, which is part of the design of the building but its covered with transparent zinc and water enters some rooms during the rainy season due to the opening. Fencing was not completely done. The center needs bore holes and quarters, doctors. The medical equipment is wasting away because of lack of medical personnel to man them.
Umuorie	Blake Excellence Resort Ltd	Bore Hole Water Scheme	2007	Tank reservoir was mounted and the borehole produced water for a short time and periodically; and this is always possible when the community provides the generator to power it. The project was never commissioned. Presently no work is going on at the site and grasses have overgrown the place.
Umuokwor	Centel Nig. Enterprises	Solar Powered Bore Hole	2007	The bore hole project was test-run for a few days after which it stopped producing water. It has not functioned since then. The project is yet to be commissioned.
Umuiku	don't know	Six Classroom Block	2005	The six classroom block has been roofed but no ceiling, no doors, no windows. It has yet to be plastered and floored. No electric wiring. No borehole.

## BAYELSA STATE

1. **Kolokuma/Opokuma LGA**: No incomplete, abandoned or substandard NDDC projects were recorded in this LGA.

2. **Sagbama LGA**:

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Odoni	Pile Foundation	Shore protection	2004/05	The level is less than ten percent complete. They only erected the poles. The poles are death traps to humans. Picture not available, it is underwater, that is the project.
Odoni	Ekegu Investment	Six classroom blocks primary school	2006	Project stopped at the roofing level.
Sagbama	no idea	Cottage Hospital	2005	The project is yet to be completed. At present it is left after roofing, plastering and flooring (tiles). But no windows, doors and electrical fittings, even the building has not been painted.
Adagbabiri	Pererich Investment	NDDC Water Project	2005 May	The tank has been installed, fenced, bore hole drilled. But the distribution network, operational equipments are not in place.

## DELTA STATE

1. **Ughelli South LGA**: No incomplete, abandoned or substandard NDDC projects were recorded in this LGA.
2. **Uvwie LGA**: No incomplete, abandoned or substandard NDDC projects were recorded in this LGA.

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Ebrumede	Chief Ugavah Ogan	Principal's Quarters, Staff Office and 3 Classroom Block	2005	The entire project has been abandoned; it was abandoned at DPC level, foundation level. NDDC visited the project and promised to help but nothing has been done yet.

3. **Warri South LGA**:

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Omadino	Kay Douglas Venture	Solar water project	2008	The water is not channeled to the community.
Obodo	A&B Mabi Nigeria Ent.	Solar water project	2007	The water project was abandoned. There is no solar plate, no machine for pumping of water, and no pipe link to the tank and consumer site.

## IMO STATE

### 1. Oguta LGA

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Ndi-Uloukwu	Frank and Green	Amawell/Awa Road	2009	The project is incomplete and abandoned because since the award of the contract nothing has been done on the road, and no sign of work starting soon on the road. Presently the road has been over flooded with water due to rainy season.
Ndi-Uloukwu	don't know	Information Technology Centre	2008	The project is a two story building. It is incomplete and abandoned because only the ground floor was decked and five blocks were added above the decking. It has no doors and windows. Presently the whole of the project site has been overgrown with grasses.
Mgbele	Peninsula Nig Ltd	Solar powered water scheme	2007	The project was abandoned after mounting the over head tank. The solar panel was not installed. The project never functioned for one day.
Mgbele	Sieako Ventures lab. Nig	Model six classrooms block	2008	The project is substandard because some of the doors and windows have started pulling out from the wall. A source confirmed that iron doors and windows was specified in the contract paper but the contractor used wooden door and windows.
Ejemekwuru	Epitome Dev. Ltd.	Model Six Classroom Block	2005	The project was abandoned at the Finishing Stage. The project was roofed, but no windows, no doors or ceiling, and no plastering.

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Umunwama-Izombe	Chief P.O. Nwosu & Sons	Model Six Classroom Block	2005	Project was abandoned at the completing stage. The building has been roofed but no windows, no doors and half plastered.
Egbuoma	don't know	Mono Pump Bore Hole	2005	The project was abandoned after mounting the pump. It never functioned for one day. Currently the whole place has been over grown with grasses.
Obudi Agwa	Niger Delta Construction Company	Obudi Agwa/ Izombe/ Egbema Road	2006	The project is currently incomplete and abandoned, only 10% of the road project was done by the contractor. Presently the road is in bad shape because motorists find it difficult to access the road.

## 2. Ohaji Egbema LGA

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Umuapu	no idea	Installation of Transformer	2007	The transformer was installed but not connected with the high tension wire.
Obitti	Enegos Int'l Co. Ltd	Electrification	2005	The transformer was installed and was never connected to the high tension wire. The project was incomplete and abandoned; it never functioned for one day.

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Obitti	Star Investment Nig. Company	Mini Water Scheme	2005	The project was abandoned at the completion stage. The water was test run during the project execution and since then never functioned for one day. The project has not been commissioned.
Etekwuru Egbema	Goldspot Nig. Ltd	Solar Powered Water Scheme	2005	The tank structure was constructed but no tank was mounted. Also the water did not rush, not even for one day.
Ihie	don't know	2 mono pump boreholes (primary school)	2008	The mono pump bore hole functioned for 2 weeks before it spoiled. The project is substandard and in need of repair.
Ihie	don't know	Public toilet (primary school)	2008	The project was abandoned at the completion stage. The plumbing work was not done properly and it is not functional.

## ONDO STATE

### 1. Ilaje LGA

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Anehin	don't know	Walk way	2007	The wooden pathway is bad and need repairing.
Anehin	don't know	Electricity	2008	The electric pole (wood type) has been erected and complete wiring likewise some street light has been fixed but there is no light at all.
Aiyetoro	don't know	Technical workshop	2006	No doors and windows. No equipment, no activities going on.
Aiyetoro	don't know	Technical school/ workshop	2006	The school /workshop was formerly built by the community before the NDDC took it over from them. It was completed and abandoned, it has started dilapidating. The equipment are lock up since the NDDC has taken it over from them. The place is now being used for another purpose (nursery and primary school) the equipment have started rusting.
Aiyetoro	don't know	Water scheme, 9 borehole well	2007	Borehole not deep enough to get to good water level. The pumping machine is not strong enough.
Aiyetoro	Gard Ashogbon & sons Nig Ltd	6 - classroom block (primary school)	2005	Incomplete and abandoned.

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Ode-Mahin	LOGTECH Ltd	Water Project	2008/2009	The well was not deep enough, solar capacity was low to carry the pump. The taps are inferior, no security, they don't hand it over to anybody in the community. All the point are worn out. The second over head tank with a bore hole was been built by an individual (Mr T.E Malomi) in 1991. It only worked for three years and the last one built by OMPADEC in 1980 is no more in use, totally abandoned.
Ilowo	Fomoyi Service ltd	Water Scheme (bore hole)	2006	The bore hole has been drilled, the iron overhead tank has been erected. Treatment chamber is not functional. It is abandoned at the stage of channeling water to the entire community. The water produced at this level for people is not safe to drink.
Ilowo	don't know	Comprehensive Health centre	2002	The wooden floor is bad, foot bridges that are the entrance to the health centre is degraded. The windows and doors has broken. The roof is leaking. Staff quarter toilet at the centre is not complete. The source of electricity is generator but no provision for fuel and repairing. Boat ambulance for emergency is bad.
Ojumole	don't know	primary school	2002	Fixing of broken windows, re-flooring, replacement of wooden wall and provision of chairs and desks
Ojumole	don't know	Teacher's Quarter	2002	Wooden floor needed to be repaired.

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Gbagira	don't know	Gbagira wooden walkway	2007	Most of the wood/plank use as covert has been weaken by water so they need to be replaced.
Rewoye	don't know	Rural Electrification	2005	Poles are erected with wire but not connected to any power source.
Rewoye	don't know	Wooden Road network	2008	Most part of the wooden foot bridge has been damaged by water. The covert are weaken which need to be replaced.
Awoye	don't know	walk way	2007	Some of the plank covert has been weaken by rain and need to be replaced.
Awoye	don't know	Second wooden walk way	2008	All the wood has been seriously damaged by water.

## 2. Ese Odo LGA

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Biagbini	Chensola Nigeria limited	Health centre	2007	The project stopped at the roofing stage, no window and doors.
Biagbini	Chensola Nigeria limited	Foot bridge/ walkway leading to the health centre	2008	They only erect the plank inside the water but it has not been covered with a covet.
Opuba	Malarlous Const. company	Six classroom wooden blocks	2007	The footbridge leads to the school is bad, toilet is collapsed, some windows and doors are broken, the ceiling boards are bad. The school need to be renovated.
Ukpe	Ofewei Nig. Enter.	six classroom block	2001	The roof are leaking, the windows and doors are breaking off.
Arogbo	don't know	water scheme (solar powered)	2008	The network pipes through the community has not been linked. The water is not running.
Akpata	don't know	solar powered water project	2008	Overhead station tank installed, bore hole drilled with only one tap. No treatment plant, distribution points to the entire community has been done. Solar panels installed. Security house has not been erected. No generator to serve as alternative source of power.
Kiribo	Lebanon Company	health centre	June 20, 2004	Roofing and plastering is completed, but windows and door are not yet fixed, partially floored, not yet fenced.

**RIVERS STATE**

1. **Ahoada East LGA**: No incomplete, abandoned or substandard NDDC projects were recorded in this LGA.

2. **Obio-Akpor LGA**

COMMUNITY NAME	CONTRACTOR NAME	PROJECT TYPE	START-ED	PROJECT STATUS
Eliozu	Chief Ejims	Eliozu Road	2008/09	No drainage system; built below specification (not properly tied)

**ABANDONED, INCOMPLETE OR SUBSTANDARD  
INFRASTRUCTURE PROJECTS**

**SPONSORED BY  
STATE GOVERNMENT**

## STATE GOVERNMENTS

### Incomplete, Abandoned, and Substandard Projects Sponsored by State Governments

[Each project status is written as it was recited to assessors. Assessments completed August through December 2010.]

(3 Geopolitical Zones, 6 States, 13 LGAs, 120 Communities)

STATE	LGA	NUMBER OF INCOMPLETE, ABANDONED AND SUBSTANDARD PROJECTS IDENTIFIED
Abia State (SE)	Ukwa East LGA	7
Abia State (SE)	Ukwa West LGA	4
Bayelsa State (SS)	Kolokuma/Opokuma LGA	16
Bayelsa State (SS)	Sagbama LGA	18
Delta State (SS)	Ughelli South LGA	7
Delta State (SS)	Uvwie LGA	5
Delta State (SS)	Warri South LGA	8
Imo State (SE)	Oguta LGA	8
Imo State (SE)	Ohaji Egbema LGA	6
Ondo State (SW)	Ese Odo LGA	20
Ondo State (SW)	Ilaje LGA	9
Rivers State (SS)	Obio-Akpor LGA	3
Rivers State (SS)	Ahoada East LGA	9
		<b>TOTAL: 120</b>

## ABIA STATE

### 1. Ukwa East LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Obuzu (Ikwoorieator West)	Abia State Universal Basic Education Board	don't know	Library	2004/2005	Some part of the building has been roofed while some has not been roofed. There is no ceiling. doors, windows, and the building has neither been floored nor plastered. Presently, a big Gmelina tree is growing in one of the rooms in the building.
Azumini	Abia State Universal Basic Education	don't know	Four Classroom Block	2008	The project has been built to lintel level. It has not been roofed, no windows, doors, and it has not been floored nor plastered. Presently the building has been overgrown with grasses.
Azumini	Abia State Government	don't know	Health Centre	don't know	The buildings are in good condition but no medical equipment, no doctor and no quarters for health workers. The water scheme at the centre is not functioning.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Obeaku	Abia State Universal Basic Education	don't know	Secondary school	2008	The building has not been roofed. Presently it is at lintel level. It has no doors, windows and it has not been plastered. It is a three classroom block with an office. It has been overgrown with grasses.
Obeaku	Abia State Universal Basic Education	don't know	Secondary school	2005	The project is a three classroom block with an office. It is at lintel level. There is no door, window, roof and it has not been plastered. The building has been overgrown with grasses.
Obeaku	Anambra-Imo River Basin	Enyinnaya Abaribe	Bore Hole Water Scheme	2008	No network pipes across the community and the whole project has not worked or functioned for a day; no water has been produced by the project.
Okotoko	ETF	don't know	Toilet in Okotoko primary school	23-Jun-09	They only dug the pit and built the structure; but they have not installed the slab and there is no borehole for the toilet.

## 2. Ukwa West LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Obehie	Abia State Universal Board of Education		Asubeb Renovated Building	2003	The ceiling is spoiled and some doors and windows have pulled out. Some part of the fence is collapsing.
Ezendioma	Abia State Government		Health Centre	2010	The contractor died, but the project stopped for almost 3 months before he died. The walls have been constructed. It has not been roofed or plastered and floored. Windows and doors are not yet fixed. Presently, the entire building has been overgrown by bush.
Umuebulungwu	Abia State Government		Health Centre	2009	The doors and windows of the centre are yet to be fixed. No single furniture or equipment. The soak away was dug but not completed. No borehole to supply water. The whole building is overgrown with grasses. No fencing.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Umuiku	Abia State Government & MDG		Health Centre	2005/2006	Windows and doors to different rooms have yet to be fixed. No toilet facilities yet. No chairs, tables or benches for patients is available. No medical equipment or patient beds available. No power supply. No water. No Staff quarters. No fencing.

## BAYELSA STATE

### 1. Kolokuma/Opokuma LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Igbedi	Bayelsa State Government	Driyai	Water Project	2009	Water is not running. The project is ongoing.
Okoloba	Bayelsa State Government	Chief Christopher Alazigha	Magistrate Court	2006	Completed, but there is no furniture inside and it has not been commissioned as such. The structure is not in use at present.
Okoloba	Bayelsa State Government	don't know	Bore Hole water scheme	don't know	The bore hole construction was completed but the distribution channels were not fixed.
Okoloba	Bayelsa State Government	Iney Dudafa	Cottage Hospital	2004	The structure has been roofed, the wiring was also partly done, but no doors or windows.
Kaiama	Bayelsa State Government	Dr. Tarila Tebipah	College of Health science	2005	Some of the buildings are left at roofing level, lintel level, window level and DPC level.
Kaiama	Bayelsa State Government	Sen. Amaitari Zuofa	2-Rooms office block	2004	Abandoned at DPC level
Kaiama	Niger Delta Basin Authority	Mr Gbasa	Bore Hole water scheme	2007	It was left at drilling stage; no other thing has been done on it till date.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Kaiama	Bayelsa State Government	Mr. Ekeh Bekekiri	6-Classroom block building	2007	It was abandoned at lintel level.
Ayibabiri	Bayelsa State Government	don't know	Road	2008	Graded not tarred.
Ayibabiri	Bayelsa State Government	no idea	Water Project	2005	The overhead tanks are already installed, but the pipes need to be put in place.
Orubiri	Bayelsa State Government	no idea	Health Centre	2001/2002	Roofing level. The structure was roofed but no door, no electricity and the toilet facility/flooring are yet to be done.
Orubiri	Bayelsa State Government	don't know	Bore Hole water scheme	2001/2002	Drilling has been done, the tank stand has been mounted, the generator house has been built with the generator perfectly mounted but the tank is still yet to be installed and the distribution channels has not been fixed.
Odi	Bayelsa State Government	don't know	NYSC Lodge	2003	no doors, no windows.
Odi	Bayelsa State Government, Ministry of Education	Lt. Col. Inokoba Romanus	Community Girls Secondary School	2007	no windows, no doors.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Odi	Bayelsa State Government, Ministry of Education	Pelfaco	Amsain Primary school	2002	At the lintel level, not yet roofed.
Odi	Bayelsa State Government, Ministry of Education	Edibass	Staff Quarters (Amsain)	2001	At roofing level.

## 2. Sagbama LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Toru-Ebeni	Bayelsa State Government	CH. Egeyi & CH. Samuel Ogugu	Hydro-Water Scheme	2005	After boring of the pipes (water channels) the second person Chief Egeyi stopped his own part of the project at roofing level. Although the drilling and raising of the overhead tank has been completed, water cannot be pumped because the electrical fittings has not been installed and the generating plant for the pumping of the water has been stolen due to the incomplete building and lack of security on site.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Toru-Ebeni	Bayelsa State Government	Akposim Nig Ltd. (Hon. Jacob Akpani)	3-Classroom block/Toilet	July 2010	Abandoned at roofing level
Toru-Ebeni	Bayelsa State Government	Setraco Ltd	Bridge	2006	Abandoned after pinning 12-pillars, the remaining 7-pillars are yet to be pinned till date.
Odoni	Bayelsa State Government	don't know	Cottage Hospital	2007	Roofed and abandoned, no doors, windows.
Odoni	Bayelsa State Government	don't know	Road Construction	2008	Some meters remaining to be covered. About 90% complete.
Odoni	Bayelsa State Government	Angbare Ebitimi	Renovation of six classroom block River Nun Sec.School	2003	no ceilings, no doors, no windows.
Odoni	Bayelsa State Government	Alade Reed	River Nun Grammar school Library	2008	Not painted, no books.
Agbere	AGIP/Bayelsa State Government	don't know	Gas Turbine (power Project)	don't know	After connection of wires to only 1km instead of the original more than 7km. It suppose to be from Idu Gas plant to Agbere Community.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Sagbama	Bayelsa State Government	don't know	Gifted Secondary School Building	2007	According to community CDC chairman, the buildings inside the site are more than ten buildings. We couldn't enter there because it was too bushy and swampy. According to him, some of the buildings are abandoned at roofing stage, decking stage and lintel stage.
Bulou-Orua	Bayelsa State Government	De-Prize Global Resources	Civic Centre	2007	the roofing work is not well done, it suppose to go round the building. Nothing was done on the floor. It is just left like that with grasses everywhere.
Bulou-Orua	Bayelsa State Government	don't know	Bore Hole water scheme	2003	Abandoned after drilling bore hole, mapping of the pillars stand and building of small engine room and never seen in the site again.
Bulou-Orua	Bayelsa State Government	don't know	Pipe Borne Water	2007/2008	Completed but with substandard material, the distribution pipes are already all gotten broken.
Ebedebiri	Bayelsa State Government	no idea	Hospital	1999	Sewage Tank has not been fixed. No electrical fittings. Building not painted.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ebedebiri	Bayelsa State Government	Chief Apena	six classroom block with headmaster office	2007	The building was abandoned at lintel level.
Ebedebiri	Bayelsa State Government	no idea	Bore Hole water scheme	2003	The drilling was done, but overhead tank has not been installed, the generator house has not been built and there is no distribution channel.
Ebedebiri	Bayelsa State Government	Chief Wanabor	Youth Corpers Lodge	2004	The building was left at window/lintel level and nothing has been done on that building till date. In fact the structure has been engulfed by bush.
Tungbo	Bayelsa State Government	Engr. Nimipere Willis	Comprehensive secondary school 3 block building	2000	The admin block was completed but there are no doors and windows and electrical work has not been done. The science block was roofed but no ceiling, windows, doors and electrical fittings have not been fixed. The classroom block was built up to roofing level and was left like that.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Toru-Angiama	Bayelsa State Government	Ebikebena Pinaowei Germany	Water Project	2004	The project was abandoned after drilling of bore hole. After that, nothing else was done. In fact, the site is so bushy and has been converted to farm land.

## DELTA STATE

### 1. Ughelli South LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ekakpamre	Ministry of Primary and Basic Education, Delta State Government	Ministry of Primary and Basic Education	Ekakpamre Primary School II	2000	The 6 classrooms in Ekakpamre Primary School is in need of repair in the area of ceiling and the roof of the building, as well as the floor and walls of the building.
Ewu	Ministry of Education, Asaba	Ministry of Education Secretariat, Asaba	Ewu Junior Grammar School	don't know	Two classrooms block abandoned at nearly lintel level.
Ewu	Delta State Oil Producing Area Development Commission (or "DESOPADEC)	Pius Eghwerido	Solar water project	2009	The water project was left incomplete. No pipes were laid, no solar plate to run the machine.
Oginibo	Urban Water Board	Jeffia	Water project	2002	The water project is left incomplete. There is no link of pipe from the water location to other streets in the community.

<b>COMMUNITY NAME</b>	<b>SPONSOR</b>	<b>CONTRACTOR</b>	<b>PROJECT TYPE</b>	<b>START-ED</b>	<b>PROJECT STATUS</b>
Oginibo	Delta State Oil producing Area development Commission	Tabmote Enterprises	Oginibo Secondary School	2010	The six classroom blocks, teacher offices and toilet was abandoned at foundation stages.
Oginibo	Delta State Government	Racoy Construction	Road Project	2002	The road project was abandoned at grading and sand filling level.
Okwagbe Waterside	Delta State Government	don't know	Okwagbe Waterside Lock Up Stores	2008	The lock up store in the community was abandoned at lintel level in some buildings while others were roofed with zinc and have no doors and plastering.

## 2. Uvwie LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ugbomro	Delta State Ministry of Works, Asaba	Raycon	Road	2009	Road not graded, not tarred, pot holes and water logged.
Ugbomro	Delta State Government	don't know	Vehicle Inspection Office building	don't know	The vehicle inspection officer (V.I.O) building was incomplete; one side of the building was roofed and the other side was not. There is bush around the building.
Ugbomro	Delta State Ministry of Youths and Sports Development	CRISG Culsan Nig. Ltd	Mini Sport Arena	2006	The pitch is bushy, the sitting areas are not covered, no seats - only blocks have been mounted. The place is being used for grazing.
Ugboroke	Delta State Ministry of Education (basics and primary)	don't know	Ugboroke Primary School	2006/2007	This is a block of two classrooms abandoned at nearly lintel level.
Ebrumede	Delta State Government	don't know	Water Project	2009	The water project is a substandard project. It only worked for just one day, since then it stopped working.

### 3. Warri South LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Usele	Delta State Government	don't know	Water Project	don't remember	A water project was abandoned at the community. There is no generator room, no laying of pipe, no tank. It was only a water tank pole/iron standing at the site.
Ekurede Itsekiri	Delta State Oil Producing Development Commission	don't know	Water Project	2010	The water project was abandoned and incomplete. There is no pipe and tap to link the water location to every street in the community.
Ugbori	Delta State Ministry of Water Resources	Mr. Austin	Water Project	2004	The water project was abandoned since 2004. There is no pipes and tap that link the various streets in the community for them to use.
Ajigba	Delta State Government	don't know	Bungalow Building	don't remember	One bungalow building was abandoned at roofing stage.
Ugbuwangue	Delta State Government, Ministry of Education	don't know	Yonwuren Junior Secondary School 1 and 11, Ugbuwangue	don't remember	Six classrooms of two block is incomplete. There are no windows, doors, ceilings and the wall is not plastered.
Ugbuwangue	DESOPADEC	don't know	Ultra modern market	Feb-10	Project left at the foundation level.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Obodo	Delta State Government	Hon. Mayuku	Solar water project	2010	The solar water project is abandoned and incomplete. There is no water tank stand, no tank, no solar plate, no link of pipe to the community and the security house was left at roofing stage.
Obodo	Delta Oil Producing Development Commission	don't know	Housing units	2005	One bungalow bedroom flat was left abandoned at the DPC level.

## IMO STATE

### 1. Oguta LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ndi-Uloukwu	QQAA	Chibuzo Nwauwa (from the community)	Rural Bore Hole (Solar Powered)	2008	The project is incomplete and abandoned because it was test run for about two or three times and since then it never functioned again. It was never commissioned and consequently was not handed over to the community. The project is substandard because the solar panel was kept on the ground instead of up. Presently the solar panel has been taken away by the contractor in order not to be stolen.
Ndionyemaobi	ISOPADEC	don't know	Mono Pump	2009	The project is substandard because they did not get water; the project has not functioned for even one day. The whole area looks deserted and overgrown with grasses. There is no sign that the contractor or those handling the project will come back to the site soonest.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ndionyemaobi	ISOPADEC	don't know	Toilet Project	2009	The toilet building was erected but the soak away was not sunk. Currently, the toilet is not functional.
Ejemekwuru	Imo State Government	don't know	Six Class Room Block	2004	The project was abandoned at the DPC level. Currently the project has been over grown by grass.
Umunwama-Izombe	ISOPADEC	Chris Onyemechi	School Toilet Project	2008	The project was abandoned at the foundation level. The project has been overgrown with grass.
Eziorsu	ISOPADEC	Catfish Consultants Nig. Ltd.	5 Compartment Table Size Fish Pond	2008	The project is incomplete and abandoned because fingerlings were never supplied to the Pond and the Pond was never connected to a water source. The fish pond has 5 compartments. Only the 5 compartments were erected. There is no borehole to supply the fish pond with water.
Aborshi-Izombe	Education Trust Fund	don't know	Four Classroom Block	2000	Project was stopped at lintel level. Building was never roofed. There are no doors or windows.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Egbuoma	Imo State Government	Peninsula Enterprises Nig. Ltd	Oguta/Egbuoma Road	2002	The project is incomplete and abandoned. The contractor graded the road and dumped some laterites and abandoned the project. It is also substandard in the sense that the drainage system is not wide enough.

## 2. Ohaji Egbema LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Obitti	ISOPADEC	don't know	Mono Pump in health centre	2008	The project is incomplete and abandoned because it never functioned for one day and presently there is no effort by sponsors of the project to complete it and make it functional.
Obitti	ISOPADEC	don't know	primary school toilet	2008	The project is not functional because there is no water connected to the toilet. The toilet has been over grown with grasses. There is a need to connect the toilet to a water source in order to make it functional. Presently the project has been abandoned.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Etekwuru Egbema	ISOPADEC	don't know	Pit Latrines Toilet at Primary School	2007	Some part of the building is roofed and the other part of the building is at the DPC level. The project is not in use.
Obosima	Universal Education Board	don't know	6 Classroom Block	2005	The building has no windows, doors, ceiling; floor is full holes.
Obiakpu	ISOPADEC	Christ Brown International Nig. Ltd	Rural Road (Obiakpu-Umuoji)	2008	Project was abandoned half-way from where the contractor was suppose to construct a culvert but he had to cut the road there. The project is substandard because of the materials used and the drainage system is not flowing.
Obokofia	Imo State Government	Imo State Govt	transformer	2008	The transformer was installed but was not connected to the high tension; consequently the transformer is not functional.

## ONDO STATE

### 1. Ese Odo LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Opuba	OSOPADEC	Mr. Oyeme Abise	Concrete Jetty	2008	The iron or rod pillars were erected but the concrete top was never added.
Opuba	OSOPADEC	Chief F.O. Ajama	wooden foot bridge	2006	The wooden bridge was to serve as network roads within the entire community but only half of the community was covered and completed.
Opuba	OSOPADEC	Chief F.O. Ajama	Six classroom wooden blocks	2008	The windows, doors and ceiling board are yet to be fixed. Some part of building has not been floored, that is, wood that serves as floor has not been fixed.
Opuba	OSOPADEC	Aroju Eregha and Sons Ltd	Electrification	2008	Project is incomplete. Only three quarters of community has been erected with wooden electricity poles and wired but remain (one quarter) have no poles. The generator plant is available but not yet connected. Now some erected poles are falling off.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Opuba	OSOPADEC	don't know	Housing units	2007	Some houses are left at various stages of incompleteness: roofing, some have only wooden pillars but no wooden wall, some are not yet roofed, some have no wooden floor, some have no windows and doors.
Ukpe	OSOPADEC	don't know	Foot wooden bridge	2008	A part of the community where the first foot bridge was constructed complain bitterly as the wooden bridge is collapsing and need repair. Another foot bridge of 900m embarked on by OSOPADEC has been stopped after construction of about 100m.
Ukpe	OSOPADEC	don't know	Teacher's staff quarter	2007	The project was left incomplete: the windows, doors, interior furnishing, floor of some part of the building (kitchen) have not yet been done.
Ukpe	OSOPADEC	ICOT Concept Ent.	Electrification	2009	Half of the community is wired and other side is not. The street light bulbs are not yet fixed. Generator plant to power the community is not available.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Arogbo	Ondo State Government	don't know	Electricity	2008	The poles have been erected and wiring is also completed but it has not been connected to light.
Arogbo	OSOPADEC	Hon. Agboola Ajayi	Embankment/ Pilling	2006	Project abandoned after piling of one quarter of the community instead of the entire community.
Akpata	Ondo State Government	Mr. T.A Omasehin	Six classroom primary school block, Akpata	2009	Building and walling have not started. Flooring is just done half-way.
Akpata	Ondo State Government	Mr. Sunday Tundia. Mr. B.O. Ominidougha, High Chief Bekewei	Wooden footbridge/ walkway	2005	Few pegs of woods have been done. The pegged woods are rotten and falling off. The work done is not up to one quarter.
Akpata	OSOPADEC	don't know	Housing Scheme	2005	Some units of houses have been built and given to some persons while the remaining units have not been completed. Walls, roofings, flooring have been completed. No windows, doors, ceilings and paintings.
Igbotu	Ondo State Government	don't know	Primary school building	2007	No walls, no windows.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Igbotu	OSOPADEC	don't know	Irere, Sabomi Igbotu Road	2005	5km of the road to Ode-Irehe was not tarred.
Igbotu	Ondo state government	don't know	six classroom (FAC Primary School)	2007	Left at limited stage, no roofs, no windows and no doors.
Kiribo	OSOPADEC	don't know	Six classrooms block at Methodist Primary School, Kiribo	2008	No windows and doors, not yet plastered.
Kiribo	OSOPADEC	don't know	Local Authority Primary School	2009	The project was abandoned at foundation level.
Kiribo	OSOPADEC	don't know	Jetty	2007	Abandoned project in which the rods had been erected as pillars and left without the concrete platform.
Kiribo	Ondo State Government	Hon. Babatunde Ayemo, former Ilaje State Assembly Representative	Pilling or Embankment/ Sandfilling	2006	The project has not commenced but the contractor has been mobilized.

## 2. Ilaje LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Aiyetoro	OSOPADEC	Oba Ilas Ikuemola	Technical School	2008	Abandoned at the roofing stage, no windows or doors. Some sections are at foundation level. Overgrown with bushes and no accessibility to the site.
Aiyetoro	OSOPADEC	Just Afrique Global Concept	Secondary school classroom (6)	2007	it was roofed without windows and doors. No floorings and plastering. Work have been stopped since 2009. It is being used like that with water filling half of the class.
Ode-Mahin	Ondo state Government (Agagu)	don't know	Primary school classroom (6)	2006	It had been roofed but no windows, plastering and or flooring. It became abandoned due to change in government from the Agagu government to Mimiko government.
Ode-Mahin	OSOPADEC	don't know	Secondary school class room (6)	2006/2007	No roofing, plastering, window, painting due to change in power from the former PDP government to the present Labour Party government. With another 3-laboratory room which were incomplete and abandoned.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ilowo	OSOPADEC	don't know	Teacher's Quarter	2009	The blocks were incomplete and abandoned. The windows and doors have not been fixed. The flooring is not completed. It is not yet plastered.
Ojumole	OSOPADEC	don't know	Residential building	2007	After erecting the main wooden pillars, the project was abandoned. No block walls, no flooring.
Ojumole	Ondo state government	don't know	primary school "6 classroom block"	2009	The wooden building is almost complete but no doors, windows, ceiling, chairs and desks.
Rewoye	OSOPADEC	don't know	Primary school (6 classroom)	2007	Abandoned at the stage of roofing. No window or door.
Rewoye	OSOPADEC	don't know	Teacher's Quarter	2008	Abandoned at the roofing stage. No windows and doors, no flooring and ceiling.

## RIVERS STATE

### 1. Ahoada East LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ikata	Rivers State Government	Mr. Dennis Onouha	Rural Electrification	2004	The project was abandoned after some poles were erected.
Odiabidi	Rivers State Government	don't know	UBE classroom blocks primary school	don't remember	No windows, no doors, no fittings.
Ihuaje	Rivers State Government	Glory Ideozu	Six Classroom Block	2005/2006	Project was abandoned after roofing.
Ihuaje	Rivers State Government	Mr. Charles / Solution Homes	Primary Health Centre	2008	The project was plastered and abandoned after being roofed.
Ogbo	River State Government	PH Investment	Ogbo Ihugbogo Road Construction	2008	Project was abandoned after elevation with latrites and pouring of chipens.
Ogbo	Rivers State Government	Hon. Osinakachukwu Ideozu	14 Classrooms Block building for primary school	2009	Project abandoned at roofing level.
Edeoha	Rivers State Government	Chief A.C Odu	Bore Hole Water Scheme	2003	Drilling has been done, over head tank was hung but no distribution channel.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Edeoha	Rivers State Government	Jolima Const. Company	Low Cost Housing Unit	2000	They just raised two structures without roofing them and left. According to what we hear, they said they were going to build market structures and police post in that site. They left after grading the whole site and since then, nothing has been done on that site. The site is suppose to be a satellite town for community.
Edeoha	Rivers State Universal Education Board	Chief Emmanuel Omokpai	Six classrooms block primary School	2003	Abandoned at D.P.C / foundation level.

## **2. Obio-Akpor LGA**

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Elikpokwuodu	Rivers State Government	Tarvis Nig Ltd	Health Centre	2008	Roofed, plastered, no electricity although it has been wired. Not yet functional.

<b>COMMUNITY NAME</b>	<b>SPONSOR</b>	<b>CONTRACTOR</b>	<b>PROJECT TYPE</b>	<b>START-ED</b>	<b>PROJECT STATUS</b>
Woji	Rivers State Government	Deacon Parker	Road 5, Fed. Housing Estate	2008	The work was abandoned after mobilization to the site. At present, the road is seriously in bad shape and needs government's immediate intervention.
Woji	Rivers State Government	Mechika Invest. Ltd.	Circular Road Construction	2008	The project was abandoned at asphaltting stage.

**ABANDONED, INCOMPLETE OR SUBSTANDARD  
INFRASTRUCTURE PROJECTS**

**SPONSORED BY**

**LOCAL GOVERNMENT AREA (LGAs)**

## LOCAL GOVERNMENT AREAS (LGAs)

### Incomplete, Abandoned, and Substandard Projects Sponsored by LGAs

[Each project status is written as it was recited to assessors. Assessments completed August through December 2010.]

(3 Geopolitical Zones, 6 States, 13 LGAs, 120 Communities)

STATE	LGA	NUMBER OF INCOMPLETE, ABANDONED AND SUBSTANDARD PROJECTS IDENTIFIED
Abia State (SE)	Ukwa East LGA	0
Abia State (SE)	Ukwa West LGA	3
Bayelsa State (SS)	Kolokuma/Opokuma LGA	1
Bayelsa State (SS)	Sagbama LGA	3
Delta State (SS)	Ughelli South LGA	8
Delta State (SS)	Uvwie LGA	3
Delta State (SS)	Warri South LGA	1
Imo State (SE)	Oguta LGA	5
Imo State (SE)	Ohaji Egbema LGA	3
Ondo State (SW)	Ese Odo LGA	0
Ondo State (SW)	Ilaje LGA	0
Rivers State (SS)	Obio-Akpor LGA	1
Rivers State (SS)	Ahoada East LGA	3
		<b>TOTAL: 31</b>

## ABIA STATE

1. **Ukwa East LGA**: No incomplete, abandoned or substandard infrastructure project was identified.

2. **Ukwa West LGA**

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Owaza	Ukwa West LGA	Supervisory Councilor Representing IPU West	Bore Hole	2008	The project rushed for one week before it got spoiled due to inferior material used. The height of the reservoir tank is so low that children can climb it and play with it. The project is also incomplete and abandoned because pipes were not completely distributed.
Owaza	Ukwa West LGA	Councilor, IPU West Ward of LGA	Borehole Water Scheme	2007	The tank reservoir has been mounted and generator house has been built but no generator set to pump the water. The entire project was left at this stage and produces no water. The contract was awarded under the Chairmanship of Chinedu Elechi as Chairman Ukwa West LGA.
Obehie	Ukwa West LGA		Solar Powered Street Lights	2008	The street lights functioned for about 2 months and then stopped. Since the project is solar powered, the bulbs are to be replaced.

## BAYELSA STATE

### 1. Kolokuma/Opokuma LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ayakoroama	Local government/ Rural development centre	no idea	Bore Hole water scheme	2002/2003	The job was completed but the water was not potable and the pumping machine was not functioning (it could not pump out water for the community people to use)

### 2. Sagbama LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Toru-Ebeni	Sagbama LGA	Former L.G Chairman, Hon. T. Edure	Comprehensive Health Centre	2004	Abandoned at roofing level.
Trofani	Sagbama LGA	Direct Labour	Town hall	2008	Stopped at lintel level for roofing.
Adagbabiri	Sagbama LGA	no idea	Community market	2007	Some of the structures have been erected while some are yet to be erected. Those that has been erected are built with inferior materials and the structure is not in use at present.

## DELTA STATE

### 1. Ughelli South LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Iwhrekan	Ughelli South LGA	Local Govt. Secretariat, Otu-Jeremi	Orhowhe Primary School, Iwhrekan	2009	6 classroom block was abandoned at the lintel level by the local government area.
Ewu	Ughelli South Local Government	don't know	Water Project	don't know	The water project was abandoned by the local government. The water project has no machine to pump the water and the pipe was not yet connected.
Oginibo	Ughelli South LGA	no idea	Water project	2004	Project was incomplete. Overhead tank and stanchion erected with bore hole drilled, but no distribution to the community.
Okwagbe Waterside	Ughelli South LGA	don't know	baba-Ido Primary school	2007	Three classroom with a staff room. The windows and doors are not yet fixed and no flooring.
Okwagbe Waterside	Ughelli South LGA	don't know	Baba-Ido Primary School Toilet Facility	2009	Is not yet plastered, the pit is not covered, the P.V.C are not yet connected to the pit.
Okwagbe Waterside	Ughelli South LGA	don't know	Baba Ido Primary school six classroom	2003	Abandoned at lintel level.

<b>COMMUNITY NAME</b>	<b>SPONSOR</b>	<b>CONTRACTOR</b>	<b>PROJECT TYPE</b>	<b>START-ED</b>	<b>PROJECT STATUS</b>
Okwagbe Waterside	Ughelli South LGA	Onomese Services	Baba Ido Primary school Twelve classroom	2009	Fixing of windows and doors, ceiling is not yet fix. They are yet to floor the ground of the classrooms.
Okwagbe Waterside	Ughelli South LGA	Olaliz International Ltd	Okwagbe Waterside Health Centre	2009	The laboratory section of the Health Centre was incomplete at roofing level.

## 2. Uvwie LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ugbomro	Delta State Ministry of Works, Asaba	Raycon	Road	2009	Road not graded, not tarred, pot holes and water lodged.
Ohorhe 1	Uvwie Local Government	don't know	Secondary School building	2005	Some of the building was incomplete while the other part of the building was abandoned. In the area of incomplete one, the building was roofed but no windows, doors and no concrete on the floor. While the abandoned one is at roofing stage and some part at D.P.C level.
Ebrumede	Uvwie Local Government	don't know	health centre	2005	The windows and doors of staff quarter at the centre are yet to be fixed. No water and electricity. The health centre building has been completed but nothing is inside, no electricity and water also. Some of the louver blade has broken and has to be replaced. The health centre is not in use for now because it has not been equipped. it was stopped at this stage and the venue has been overgrown with bush.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Alaka	Uvwie Local Government	Mr. Solomon Ighrekpata	Water project	2010	The water project was abandoned and incomplete. There is no link of pipe between the tank and tap.

### 3. Warri South LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Obodo	Warri South LGA	don't know	Water Project	2000	The water project was abandoned by the local government. There is no pipe link to the community and no machine to operate.

## IMO STATE

### 1. Oguta LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ndi-Uloukwu	Oguta LGA	Lizans Enterprises Nig.	Rural Borehole	2007	The project is incomplete and abandoned because there is no tap and water came out from the Sumor only once and since then there is no water. The generating set is far from the borehole and it has not been installed. The project is substandard because the tank holder have visible signs of collapsing if the tanks on top of it are filled with water.
Egwe	Oguta LGA	don't know	Rural Bore Hole	2003	The tank holder was never constructed and the tank was never mounted. The only thing observed with the project was when the councilor representing the ward used a bucket to fetch water from the borehole. After that, nothing happened only to wake up one morning and discover that the borehole had been sand filled and a pole mounted on where they got the water.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ejemekwuru	Oguta LGA	Raymond Okeke	Renovation of the Dispensary	2007	The renovation exercise was never completed and half of the building that was roofed has collapsed. Presently the whole area has been overgrown with grasses.
Ejemekwuru	Oguta LGA	Oguta LGA	Farm Implements	2000	The aim of the project was to produce locally the farm implements, such as hoes, hatchets, rakes, spades, etc. The project is incomplete because the structure or house for the project was built, but it was never equipped for producing the farm implements. Presently, some part of the building has collapsed and the whole area has been overgrown with grasses.
Aborshi-Izombe	Oguta LGA	don't know	Rural Borehole	2001	Only the tank holder was constructed and those who drilled the borehole did not get water before abandoning the borehole. A Gee Pee tank was mounted on the tank holder; but not the Gee Pee tank has been stolen. The bore hole never functioned one day.

## 2. Ohaji Egbema LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Umuagwo	Ohaji Egbema LGA	Romics Nig. Ltd	Old Owerri Road	2006	The road was abandoned after the first grading. A source confirmed that the contractor have been paid for the job before he abandoned it.
Opuoma	Ohaji Egbema LGA	Stanley Peters-Pestsan & Co. Ltd., under leadership of Hon. Luke Chukwu	4 Classroom Block Building	2007	The project was abandoned at the roofing level. Not roofed, no windows, no doors, not plastered. The contract was awarded under the leadership of Hon. Luke O. Chukwu.
Obokofia	Ohaji Egbema LGA	Hon. Luke Chukwu	2 Mono pumps	2009	The pumps were just erected without getting water. The pumps did not function for even one day.

## ONDO STATE

1. **Ese Odo LGA**: No abandoned, incomplete or substandard infrastructure projects identified.
2. **Ilaje LGA**: No abandoned, incomplete or substandard infrastructure projects identified.

## RIVERS STATE

### 1. Ahoada East LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ihuowo	Ahoada East LGA	Chief Ebenezer Ogolo (late)	Drainage	2002	The project was abandoned after pouring the gravel on the ground.
Okporowo	Ahoada East LGA	Hon. Joy Oguzor	Community Secondary School Technical Workshop	don't remember	No equipment supplied, not floored, no doors, no windows, not plastered.
Edeoha	Ahoada East LGA	Chief Eke Kingdom	Edeoha Community Market	2000	Abandoned at D.P.C / foundation level

### 2. Obio/Akpor LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Choba	Obio/Akpor LGA	no idea	Igbogo Road Linking E/W Road	2005/2006	Abandoned after pouring of laterats.

**ABANDONED, INCOMPLETE OR SUBSTANDARD  
INFRASTRUCTURE PROJECTS**

**SPONSORED BY**

**OIL COMPANIES**

## OIL COMPANIES

### Incomplete, Abandoned, and Substandard Projects Sponsored by Oil Companies

[Each project status is written as it was recited to assessors. Assessments completed August through December 2010.]

(3 Geopolitical Zones, 6 States, 13 LGAs, 120 Communities)

STATE	LGA	NUMBER OF INCOMPLETE, ABANDONED AND SUBSTANDARD PROJECTS IDENTIFIED
Abia State (SE)	Ukwa East LGA	1
Abia State (SE)	Ukwa West LGA	11
Bayelsa State (SS)	Kolokuma/Opokuma LGA	0
Bayelsa State (SS)	Sagbama LGA	0
Delta State (SS)	Ughelli South LGA	0
Delta State (SS)	Uvwie LGA	0
Delta State (SS)	Warri South LGA	0
Imo State (SE)	Oguta LGA	3
Imo State (SE)	Ohaji Egbema LGA	4
Ondo State (SW)	Ese Odo LGA	0
Ondo State (SW)	Ilaje LGA	3
Rivers State (SS)	Obio-Akpor LGA	0
Rivers State (SS)	Ahoada East LGA	0
		<b>TOTAL: 22</b>

## ABIA STATE

1. **Ukwa East LGA**: No incomplete, abandoned or substandard infrastructure project was identified.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Azumini	Unknown "Gas Company"	don't know	Five Classroom Blocks	2009	The project was stopped and abandoned without roof, windows, doors, yet to be plastered. The project has over grown by bush.

2. **Ukwa West LGA**

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Owaza	SPDC	HRH Eze Young Ogbonna	Market and Cold Room with Bore Hole	2005	The cold room was functional for one year before the Royal Majesty and the wife connived and sold it to a private company. The project was done by SPDC in order to empower the women of the community to have alternative source of income. Presently, the women no longer benefit from the project. The borehole functioned for some time before it stopped so it is in need of repair. When NIDPRODEV visited the site, the cold room gate was locked.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Owaza	SPDC	HRH Eze Obioma	Ten Million Naira Primary School Project (Owaza (Etitioha))	2009	There is no substantive work going on in the site. Only molded blocks and heaps of sand were seen at the site of the project.
Owaza	SPDC	HRH Eze Young Ogbonna, HRH Eze Obioma, HRH Chinemeze Mathew, and HRH Jonathan Ezere	Electricity Upgrade from Afam to Owaza	2007	The contract was given to 4 traditional rulers but the contract was never executed. The project is worth 53.5 million naira.
Owaza	SPDC	HR Eze Chinemeze Mathew	Ten Million Naira Primary School Project (Owaza (Isietioha))	2009	Blocks were molded and trips of sand dumped at the project site. No foundation and no work is going on at the project site.
Owaza	SPDC	HRM Eze Young Ogbonna	45.5 million naira Water Project	1999/2000	Pipes were not completely laid. The project did not produce water, not even for one day. The generator house was built but no generator to power it. Pipes were packed in the contractors house and were later sold.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Owaza	Nigeria Gas Company Limited (subsidiary of NNPC)		Bore Hole	2008	The borehole was drilled and it was functional for about 6 months before it got spoiled. The major problem is that there is no sustainability plan.
Owaza	SPDC	HRH Eze Jonathan Ezere	Primary School Building (Owaza, Igiukwu)	2009	The project was awarded at cost of 10 million naira. The only visible things at the site are: blocks and heaps of sand. Presently no work is going on at the site.
Umuorie	SPDC		Bore Hole	2007	The bore hole was drilled and reservoir tank mounted but the water produced by the bore hole is not good. So some community members took the Shell Company to court. Presently, the case is still in the court and the whole place looks deserted and abandoned.
Umuorie	SPDC		Cold Room	2007	After completion of the project with facilities installed at the centre, it was test-run. After the test run, it did not function again.
Umuorie	SPDC		Road Construction	2002	The road has been tarred but no drainage system. This has allowed flooding to impact the road and causing small cracks.

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Umuorie	SPDC		Electrification	2002	This project functioned for 2 weeks after which the transformer was faulty. Since then, no power supply from the project to the community.

## **BAYELSA STATE**

1. **Kolokuma/Opokuma LGA:** No incomplete, abandoned or substandard infrastructure development identified.
2. **Sagbama LGA:** No incomplete, abandoned or substandard infrastructure development identified.

## DELTA STATE

1. **Ughelli South LGA**: No abandoned, incomplete or substandard infrastructure projects identified.
2. **Uvwie LGA**: No abandoned, incomplete or substandard infrastructure projects identified.

## IMO STATE

### 1. Oguta LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Mgbele	SPDC	MIFE	Okwu Oji/Oguta Model Road	2004	The project was abandoned at the middle of the road, where the contractor was suppose to construct a bridge. The project is also substandard because where the contractor was suppose to construct drainage system was not the place he did it.
Umunwama-Izombe	NNPC/ Chevron Joint Venture	don't know	Borehole and Overhead Tank	2006	Project was completed and test run then, but currently it is abandoned and incomplete because there is no provision for a generating set to power the bore hole. The project is non functioning because of lack of electrical power.
Eziorsu	SPDC	don't know	Six Classroom Block (secondary school)	2000	The project was abandoned at the finishing stage. The building has no windows, no doors, and has not been plastered.

## 2. Ohaji Egbema LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Etekwuru Egbema	AGIP	Christ Brown International	Water Project	1998	The contractor installed the overhead tank and left.
Etekwuru Egbema	AGIP	Christ Brown International	Etekwuru 182 Link Road (5 km)	2002	The road was abandoned after the grading and the link bridge between the two communities was not constructed.
Obokofia	SPDC	don't know	Solar Energy Borehole	early 2009	The project was substandard; it functioned for only about 3 months.
Obokofia	SPDC	Seaworld Nigeria Limited	3 Dwarf market stores	2009	The project was abandoned at the foundation level.

NOTE: Contractor Christ Brown International also is identified as the contractor on an abandoned 2008 ISOPADEC contract to construct a rural road in Obiakpu Community, Ohaji Egbema LGA.

## ONDO STATE

1. **Ese Odo LGA**: No abandoned, incomplete or substandard infrastructure projects identified.

### 2. **Ilaje LGA**

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Mese	Chevron, Ilaje RDC	Adeseg Ehinmola Nig Enterprises	Foot Bridge	2009	The bridges do not lead to each other. It was abandoned and it has not been put to use.
Rewoye	Chevron, Ilaje RDC	don't know	Public toilet	2009	The toilet has been roofed and plastered but the water system has not been connected to the suck away so it has not yet been put to use.
Awoye	Express Oil Company	don't know	Water Project	2002	The project was abandoned at the pumping stage. The water project has never been put to use.

## RIVERS STATE

1. **Ahoda East LGA**: No abandoned, incomplete or substandard infrastructure projects were identified.
2. **Obio/Akpor LGA**: No abandoned, incomplete or substandard infrastructure projects were identified.

**ABANDONED, INCOMPLETE OR SUBSTANDARD  
INFRASTRUCTURE PROJECTS**

**SPONSORED or CO-SPONSORED BY**

**INTERNATIONAL ORGANIZATIONS**

## INTERNATIONAL ORGANIZATIONS

### Incomplete, Abandoned, and Substandard Projects Sponsored by International Organizations

[Each project status is written as it was recited to assessors. Assessments completed August through December 2010.]

(3 Geopolitical Zones, 6 States, 13 LGAs, 120 Communities)

STATE	LGA	NUMBER OF INCOMPLETE, ABANDONED AND SUBSTANDARD PROJECTS IDENTIFIED
Abia State (SE)	Ukwa East LGA	1
Abia State (SE)	Ukwa West LGA	2
Bayelsa State (SS)	Kolokuma/Opokuma LGA	3
Bayelsa State (SS)	Sagbama LGA	4
Delta State (SS)	Ughelli South LGA	0
Delta State (SS)	Uvwie LGA	1
Delta State (SS)	Warri South LGA	0
Imo State (SE)	Oguta LGA	2
Imo State (SE)	Ohaji Egbema LGA	2
Ondo State (SW)	Ese Odo LGA	1
Ondo State (SW)	Ollaje LGA	1
Rivers State (SS)	Obio-Akpor LGA	0
Rivers State (SS)	Ahoada East LGA	0
		<b>TOTAL: 17</b>

## ABIA STATE

### 1. *Ukwa East LGA*

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Obuozu (Ikwuorieator West)	EU MPP6 and Obuozu Community	don't know	Health Centre	2007	The Health Centre was built by the community and EU MPP6. The building is completed and it is in good shape, but it is not functional. There is no medical equipment, drugs or water at the centre. Doctor and other medical personnel are also needed. The centre is yet to be fenced, and staff quarters is also needed. There is no security personnel at the centre.

### 2. *Ukwa West LGA*

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Umuiku	MDG and Abia State Government	don't know	Health Centre	2005/2006	Windows and doors to different rooms have yet to be fixed. No toilet facilities yet. No chairs, tables or benches for patients is available. No medical equipment or patient beds available. No power supply. No water. No staff quarters. No fencing.
Umuebulungwu	UNICEF	don't know	Mono Pump	2000	A mono pump did not function for even one day, which means that they did not dig deep enough to get water.

## BAYELSA STATE

### 1. Kolokuma/Opokuma LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ayakoroama	LEEMP (World Bank Assisted Project)	direct labour	Youth Corps Members Lodge	2008	The structure has been roofed, ceiling, plastered. Windows and doors have been fixed but not painted. Electrical fittings have not been fixed and the toilet facility has not also been fixed.
Odi	World Bank	De-Cleja	Imgbela Primary School Library	2006	No doors. No windows.
Olobiri	LEEMP (World Bank Assisted Project)	direct labour	Community primary school, Olobiri	2006	No doors. No windows.

### 2. Sagbama LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Odoni	LEEMP (World Bank)	Dr. Sunny Opukri	Water Project	2007	The project is substandard because water is not good for drinking.
Adagbabiri	World Bank Assisted Project	Former Headmaster (Jofrey Omolo)	Primary School Library	2005	Abandoned at lintel level and the construction rods/sands have been washed away by flood while the rods were sold out to some community persons.

<b>COMMUNITY NAME</b>	<b>SPONSOR</b>	<b>CONTRACTOR</b>	<b>PROJECT TYPE</b>	<b>START-ED</b>	<b>PROJECT STATUS</b>
Sagbama	UNDP and Community	Direct Labour	Renovation of market stalls	2010	The project is in progress, some part of it (six buildings) have been completed while the community is waiting for funds from UNDP to complete the remaining six buildings.
Bulou-Orua	LEEMP (World Bank Assisted Project)	Direct Labour	Modern Market Structure	2007	The structure has been completed but the environment is still swampy and yet to be worked on (sandfill or German floored). So the market is yet to be used by the community people although it has been commissioned.
Toru-Angiama	MPP3 (EU)	no idea	Bore hole water project	2004	The bore hole project was completed and even functioned for a while before the pumping machine got spoilt and the pipes (water channels) started breaking.

**DELTA STATE**

1. **Ughelli South LGA**: No incomplete, abandoned or substandard project was identified.

2. **Uvwie LGA**

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Alaka	MDG	don't know	Water Project	2008	The water project is a substandard project, because the water only worked for one week and stopped working since the project was commissioned, and water pipe does not link to other streets in the community.

3. **Warri South LGA**: No incomplete, abandoned or substandard project was identified.

## IMO STATE

### 1. Oguta LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Ndionyemaobi	World Bank Assisted and Community / MPP6	direct labour	6 Classroom Block	2008	The project was abandoned at the lintel level. The project was carried out as an agreement between the two parties: MPP6 and the community. The project was not properly planned and the community people were not properly educated on how the project will be executed.
Aborshi-Izombe	World Bank Assisted and Community / MPP6	direct labour	Borehole	2006	The borehole was test run without being commissioned. There is no provision for generating set to power the borehole. After test running the project, the bore hole never functioned again.

### 2. Ohaji Egbema LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Umuapu	LEEMP, World Bank Assisted	LEEMP	Installation of Transformer	2008	The transformer has not been connected with the high tension wire which will make it distribute light to the people.
Umuagwo	FADAMA, World Bank Assisted	don't know	Public Toilet	2006	The toilet building was completed, but the plumbing work was not done before the project was abandoned.

## ONDO STATE

### 1. Ese Odo LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Biagbini	EU	don't know	4 Block Classroom	2007	No walls, roof, or flooring.

### 2. Ilaje LGA

COMMUNITY NAME	SPONSOR	CONTRACTOR	PROJECT TYPE	START-ED	PROJECT STATUS
Aiyetoro	MDG	don't know	Town Hall	2008	No roofing, is at limited level.

## RIVERS STATE

1. **Ahoada East LGA**: No incomplete, abandoned or substandard infrastructure projects by international donors were identified.
2. **Obio-Akpor LGA**: No incomplete, abandoned or substandard infrastructure projects by international donors were identified.